	Hits	Search Text	DBs
1	255	firmware with active	USPAT; US-PGPUB
2	8	(firmware with active) and (713/1 or 713/2)	USPAT; US-PGPUB
3	1538	firmware with (updat\$3 or upgrad\$3)	USPAT; US-PGPUB
4	115	(firmware with (updat\$3 or upgrad\$3)) and (713/1 or 713/2)	USPAT; US-PGPUB
5	11	firmware with active	EPO; JPO
6	1	firmware with active	IBM_TDB
7	161	firmware with (updat\$3 or upgrad\$3)	EPO; JPO
8	10	firmware with (updat\$3 or upgrad\$3)	IBM_TDB
9	1	(firmware with (updat\$3 or upgrad\$3)) and active	EPO; JPO
10	0	<pre>(firmware with (updat\$3 or upgrad\$3)) and (second adj (firmware or space or area))</pre>	EPO; JPO
11	7	(firmware with (updat\$3 or upgrad\$3)) and copy\$3	EPO; JPO
12	3	(firmware with (updat\$3 or upgrad\$3)) and second	EPO; JPO
13	0	(firmware with (updat\$3 or upgrad\$3)) and back\$lup	EPO; JPO
14	17	firmware and back\$lup	EPO; JPO
15	75	firmware with back\$lup	USPAT; US-PGPUB
16	6	firmware with back\$lup with error	USPAT; US-PGPUB
17	1	firmware with back\$1up with \$2valid\$3	USPAT; US-PGPUB
18	1	(firmware with back\$1up) same (firmware with \$2valid\$3)	USPAT; US-PGPUB
19	6	(firmware with copy) same (firmware with \$2valid\$3)	USPAT; US-PGPUB
20	13	firmware with copy with error	USPAT; US-PGPUB
21	26	(firmware with copy) same error	USPAT; US-PGPUB
22	6	((boot adj code) with copy) same error	USPAT; US-PGPUB
23	44	((boot adj code) with copy)	USPAT; US-PGPUB